
Project 4A – Primer on Existing Walls

Sean Molloy


C20445642

PRIMER ON EXISTING WALLS

(1990 - 2000) PETACHED HOUSE - FULL FILL CAVITY WALLS - ALL ESTIMATIONS



BOND PATTERN




COMPARISON	OF	OTHER	ELEM	ients
------------	----	-------	------	-------

ELEMENT	my house	TABULA
ROOFS	PITCHED, INSULATION BETWEEN JOISTS	PITCHED, INSULATION BETWEEN JOISTS
FLOORS	SOLID	SOLID
WINDOWS	DOUBLE GLAZED IPVC	DOUBLE GLAZED / PVC
DOORS	SOLID WOODEN	SOLID WOODEN

CONCLUSION

BASED ON MY ESTIMATES , MY OWN HOUSE IS SLIGHTLY MORE ENERGY EFFICIENT THAN THE TABULA EXAMPLE (DETACHED HOUSE, CAVITY WALLS 2005 - 2010). MOST BUILDING ELEMENTS ARE THE SAME, APART FROM THE WALLS.



ESTIMATES OF WINDOW HEAD AND CILL

SEAN MOLLOY
PROJECT 4A
25 - 11 - 20




Window Details – Exterior and Interior

Brick Outer Leaf – 100mm

Window Width – 80mm

Interior- Insulation and Block – 180mm





Door Details – Front and Back Door

Front Door:

Interior – 60mm

Door Frame – 100mm

Exterior (to porch door) – 940mm


Back Door:

Interior – 130mm

Door Frame – 100mm

Exterior – 110mm





Front Elevation

- Brickwork Stretcher Bond and Lintel over Porch door.
- Pebbledash external finish from roof down.
- Plinth at bottom to protect against water ingress.
- Vent also show at top right.