

Linenhall Redevelopment Project TDS: T4 Macro Stakeholder Report 12/02/2021

Liam Deguara, Jamie Leonard, Sinéad Kielty, Karolina Potocka & Kevin O'Toole Year 4 Architectural Technology, Dublin School of Architecture, TU Dublin

mber	Item	Photo	Quantity	Condition	Notes	Material Category	Condition Evaluator	Material Categories
21112/21	inerii.	111010	additing	Condition		material Gategory	Condition Evaluator	material Galegones
1	Sockets		9		Located on walls of corridors.	Electronic	Good	Wood
2	Light Switches	•• • ••	28		Located on walls of corridors. Some switches are cracked.	Electronic	Average	Plastic
3	Ceiling Light	17	19		Tubular and circular types. 3 not working in ladies bathrooms.	Electronic	Requires Certified Inspection	Textile
4	ID Card NFC Pad		4		Located outside doors of studios to gain access.	Electronic	Bad	Metal
5	Security Keypad	200	3		Located outside doors of offices to gain access.	Electronic		Glass
6	Emergency Lighting	-*	30		Signage, tubular and box lights.	Electronic		Electronic
7	Fire System Board		4		Located above every water hose.	Electronic		Stone
8	Fire Bell	9	7		Modern and old bells distributed around the building.	Electronic		Systems
Ð	Smoke / Fire Detector	Ô	9		Located on ceilings.	Electronic		Chemical
10	Fire Break Glass		4		Beside every water hose.	Glass		Organic
11	Fire Extinguisher	(3		Powder outside the workshops and foam in the corridors	Metal		Paper & Cardboard
12	Water Hose		4		Located at the both ends of each main corridor	Systems		Ceramic

DS

DUBLIN

TECHNOLOGICAL UNIVERSITY DUBLIN